

[at%X]	Z [e/a]	T _c [K]	Ref	T _k [K]	Ref	r [mWcm]	Ref	1/r d r/dt [10 ⁻⁵ /K]	Ref	R _H [10 ⁻¹¹ m ³ /As]	Ref	S ^l (T)/T [nV/K ²]	Ref
0				15	1								
9				151	1								
10				165	1								
11				143	1								
15				190	1								
17				208	1								
72				456	1								
76				458	1								
84				397	1								

Caption:

- Z indicates the mean electron number per atom
 T_c indicates the transition to the superconducting state
 T_k indicates the crystallization temperature
 ρ indicates the specific resistivity at T approx. 4K
 1/ρ dp/dt indicates the temperature coefficient at approx. T=100K
 R_H indicates the Hallcoefficient at approx. T=10K
 S^l(T)/T indicates the slope of the thermopower at low T
 The horizontal thin lines enclose the amorphous range

References:

- [1] P. Haeussler

The concentration range between the thin horizontal lines shows the amorphous alloys, outside the samples are partly are completely crystalline.